		Or	nsite Water Prot	NMENTAL HEALT ection Notices of bber 2021			LEGEND RED - Indicates updates since last report PURPLE - Indicates County Attorney Action Requested/Legal Remedy	
NOV DATE	SUBJECT PROPERTY ADDRESS	TYPE OF VIOLATION	NOV EXPIRATION DATE	FORWARDED TO CO. ATTY?	COMPLIANCE STATUS (YES/NO)	COMPLIANCE DATE	NOTES	
9/28/2015 8/4/2021 10/11/2021	6101 Cheek Rd	No Subsurface Operator	10/28/2015 9/6/2021 11/11/2021	Y	Ν		EH has not received system management reports as required by rule. **THIRD NOTICE HAND DELIVERED 10/11/2021**	2/19/2016 - 10-day demand letter issued by County Attorney's Office. 9/30/2016 - EH will follow-up with owner on progress prior to initiation of legal action. NOV to be revisited in 30 days. 3/8/2017 - Requested County Attorney to file lawsuit . 8/31/2018 - System remains non- compliant. No ORC reports have been received as required by rule. 9/30/2018 - System remains non-compliant. Second NOV issued 8/4/2021. EH did not receive USPS return receipt for 2nd notice. 3rd notice hand delivered to site and to home address of property owner 10/11/2021.
1/7/2020	8 Steepleton	Surface Discharge	2/7/2020	Y	Ν		Surfacing effluent over pretreatment media and malfunctioning pump controls observed during regular monitoring inspection. System type is pretreated subsurface drip irrigation.	2/27/2020 - EH contacted the system operator for an update. Operator stated owner has signed a work order to repair/replace the malfunctioning control panel and pretreatment media. Scheduling TBD. 5/4/2020 - Per the septic installer, the owner has postponed repair. File forwarded to County Attorney's Office with request for a 10-day demand letter. 12/17/2020 10-day demand letter issued 12/31/2020. Septic contractor notified EHS a price quote for repair will be sent to owner 1/28/2021. Owner is working with installer and has reached out to an engineer to determine potential options for pretreatment alternatives to existing peat modules. 2/23/2021 Contractor states they are still working on quote for pretreatment alternatives. 4/29/2021 EHS contacted septic installer regarding system progress. Contractor has yet to provide a bid. EHS encouraged the contractor to prioritize this project. 8/2/2021 Owner has submitted an application for repair permit. EHS will evaluate parcel to determine if an innovative system type may be utilized to repair/replace the existing failing drip irrigation system 9/29/2021 Owner contacted EHS, states they will be replacing the peat modules with synthetic media. Design proposal from PE forthcoming. 10/11/2021
2/20/2020 9/1/2021		Surfacing Effluent	3/23/2020 10/1/2021	N	N		Existing system is failing. Property owner submitted an application for repair and a construction authorization for installation of a replacement system was issued concurrently with this notice of violation.	2/26/2021 - House is unoccupied, under renovation. Septic repair is pending. Site visit by EHS on 8/10/2021 revealed home has been reoccupied, EHS e-mailed owner for confirmation. Owner states she has not been able to hire a contractor to install system. NOV will be reissued if no progress by 9/1/2021. Second NOV issued 9/1/2021. 10/8/2021 - Owner messaged EHS with an update. Owner is arranging financing for system repair.

7/15/2020	802 Hanson Rd	Surfacing Effluent	8/14/2020	Ν	N	Property owner contacted EH and acknowledged receipt of the NOV. Owner stated she is soliciting bids from plumbers to install the sewer connection. 8/17/2020 EHS directed owner to pump tank as necessar to prevent discharge of effluent until such time owner is able to connect to sewer. 9/17/2020 EHS contacted owner for an update. Owner responded they are managing the malfunction and are workin on funding for the sewer connection with hopes to complete it within the year. 2/25/2021
9/25/2020	3419 S Alston	Straight Pipe discharge to stream and discharge to ground surface.	10/25/2020	Y	Ν	Property owner contacted EH and stated he will explore the possibilit of connecting to public sewer. 9/29/2020 EHS observed and documented unpermitted repair work on system during a site visit. System continues to discharge effluent 12/11/2020. File forwarded t County Attorney's Office with request for a 10-day demand letter. 12/17/2020 10-day demand letter issued 12/31/2020. Site has bee classified as unsuitable for repair. Owner is in contact with City Public Works to determine engineering requirements for sewer extension. EHS has directed owner to temporarily pump and haul to abate discharge of effluent while sewer extension is explored. 1/21/2021. Application for sewer extension agreement has been submitted to Cit Public Works and is pending review as of 3/31/2021. Owner has retained services of an engineer and is meeting with utility contractor to bid the project. Septic tank is being pumped as necessary to preve discharge. 4/27/2021 Sewer connection extension agreement has been approved by City of Durham. Application for plumbing permit has been approved by City of Durham. Application for plumbing permit has not yet been submitted 10/29/2021.
7/13/2021	5223 Ephesus Church Rd	Surfacing Effluent	8/13/2021	N	N	Existing system was flooded by City water system maintenance. EHS contacted owner for an update, left voicemail. 9/30/2021 Letter received from an engineering firm stating they are actively working or the drainfield. Connection to public sewer will be facilitated by City of Durham. EHS contacted owner for an update, left voicemail. 9/30/2021 Letter received from an engineering firm stating they are actively working or the sewer extension design and will be submitting plans to the City of Durham. EHS discussed situation with property manager. Succession growth must be cleared prior to repair evaluation. Property manager instructed to provide receipts for temporary pump and haul until such
7/22/2021	213 Snow Hill Rd	Surfacing Effluent	8/23/2021	Y	Ν	time the system is repaired. Septic tank was pumped 7/26/2021. Property manager contacted EHS and stated owner is refusing to submit an application for repair. 8/19/2021. File will be forwarded to County Attorney for legal remedy. 9/2/2021 - File forwarded to County Attorney's Office.

7/22/2021	6032 Burgundy Rd	Pump malfunction	8/23/2021	Ν	Y	Pump malfunction discovered during routing monitoring visit. Effluent is backing up into the pump tank freeboard and riser. Owner directed to contact a certified septic installer to repair the pump.	10/11/2021 - File forwarded to County Attorney's Office with request for demand letter. 10-day demand letter issued 10/22/2021.

ENVIRONMENTAL HEALTH

Onsite Water Protection - Compliant NOVs

July 2021 - June 2022

			July 202	1 - Julie 2022				
NOV DATE	SUBJECT PROPERTY ADDRESS	TYPE OF VIOLATION	NOV EXPIRATION DATE	FORWARDED TO CO. ATTY?	COMPLIANCE STATUS (YES/NO)	COMPLIANCE DATE	NOTES	
6/25/2015 8/3/2021	5114 Leesville Rd	Surfacing effluent, straight pipe from basement plumbing, and property line setback violation	7/25/2015 9/3/2021	Y	Y	10/14/2021	Existing system crosses property line and is discharging effluent to the ground surface. Basement plumbing is discharging via straight pipe into gutter drain. Repair permit issued same day as NOV. **Basement plumbing removed and	EHS and expressed dismay that system was not in compliance despite
2/26/2021	143 Twin Oaks Dr	Surfacing Effluent	3/26/2021	Ν	Y	10/14/2021	Effluent is surfacing above tank and throughout drainfield. Public sewer is	Owner has contacted City regarding sewer connection process. EH provided owner with an application for septic tank abandonment. 4/10/2021 No sewer permit application in LDO. EHS to make a follow up site visit in October. If malfunction is observed a second NOV will be issued. 9/30/2021

								-
9/22/2021	1014 Stallings Rd	Straight Pipe	10/22/2021	N	Y	10/11/2021	During a site visit for a well permit evaluation, EHS discovered the septic tank has been fitted with a sump pump that is discharging effluent directly to the ground surface. Owner directed to remove pump, temporarily pump and haul, and hire a certified septic contractor to determine existing septic system type prior to any permitting activity. **House has been vacated and the pump with straight pipe has been removed.**	
4/28/2021	7011 Russell Rd	Surfacing Effluent	5/30/2021	Ν	Y	10/6/2021	Complaint investigation confirmed discharge of effluent from vicinity of septic tank. Effluent is flowing onto neighboring property. Owner has submitted an application for repair permit. *Drainfield repaired , discharge of effluent has been abated.**	Repair permit issued for exploratory dig 5/4/2021. Septic contractor on site and repair in progress as of 9/30/2021.
1/26/2021	3136 E Geer St	Surfacing Effluent	2/26/2021	N	Y	9/30/2021	Complaint received regarding failing septic system. Complaint investigation by EHS confirmed discharge of effluent. **Supply line/clean out repair by owner. Discharge has been abated. **	Repair permit application submitted by owner. Permit for exploratory dig has been issued. 2/16/2021. Follow-up e-mail sent to owner with a copy of repair permit. E-mail reiterated that owner must contact a certified contractor to repair the system. 6/9/2021
8/12/2021	1224 Bramble Dr	Unapproved Pump Controls	9/16/2021	Ν	Y	9/13/2021	During a routine monitoring inspection EHS observed that effluent pump has been replaced and is connected to house power by an extension cord. Owner directed to hire a contractor to properly wire pump controls within a watertight, corrosion-resistant outside enclosure. **Permanent power has been restored to the system**	
10/28/2015 8/4/2021	5 3050 Ruth St	No Subsurface Operator	11/27/2015 9/6/2021	Y	Y	9/7/2021	EH has not received system management reports as required by rule. **Homeowner has signed a contract with a certified operator as required by rule.**	9/30/2016 - Requested 10-day demand letter from County Attorney's office. 9/30/2016 - EH will follow-up with owner on progress prior to initiation of legal action. NOV to be revisited in 30 days. 3/8/2017 - Requested County Attorney file lawsuit . 8/31/2018 - System remains non-compliant. No ORC reports have been received as required by rule. 9/30/2018 - System remains non-compliant. Second NOV issued 8/4/2021. Homeowner contacted EHS requesting list of certified operators 8/19/2021.
							Sewage is backing up into septic tank. Previous bootleg work on system appears to have resulted in part of the drainfield being disconnected and repurposed to receive water from gutter downspouts. Application for repair permit has been received. Property lines must be marked prior to issuing permit for replacement	
7/1/2021	1919 So Hi Dr	Sewage Back Up	8/2/2021	Ν	Y	8/31/2021	drainfield. **Repair system installed**	Repair permit issued 7/9/2021.

12/18/2020	2717 Comontor Bd	Surfacing Effluent	1/18/2021	Y	Y	8/12/2021	Complaint received regarding failing septic system. Complaint investigation by EHS confirmed discharge of effluent. **Flow was restored to the drainfield with the installation of a new distribution box and extensive	Owner contacted EHS stating a repair application will be submitted 1/21/2021. Owner contacted EHS stating she has contacted a septic installer and will be submitting an application for repair permit. 2/19/2021 Complaint received 3/31/2021 from neighboring property owner regarding continued discharge of effluent and illegal building activity on lot. EHS will follow-up with owner 4/1/2021 and forward to County Attorney if necessary. File forwarded to County Attorney's office 4/5/2021. Owner submitted repair application to EH 4/26/2021. Permit for exploratory dig issued 4/30/2021. Additional complaint of sewage odor and discharge received from neighbor. EHS visited site and instructed property owner to have the tank pumped to prevent discharge. Owner stated that septic installer is scheduled to work on system during the first week of June 5/25/2021 Follow-up site visit by EH confirmed discharge of effluent is ongoing. Photographs and latest complaint message forwarded to County Attorney's Office. 6/8/2021 Second notice issued that includes directive to temporarily pump & haul and to effect repairs as permitted. Notice also includes additional language regarding administrative penalty of \$50/day for non-compliance 7/15/2021. Property owner to immediately have the septic tank pumped and to arrange for a septic contractor to evaluate the mafunction account 7/15/2021.
7/15/2021 8/3/2021	2717 Carpenter Rd 4403 Pope Rd	Surfacing Effluent	8/16/2021 9/3/2021	N	Y	8/13/2021	clogged pipe repair within the exiting seepage beds.** Complaint investigation confirmed discharge of effluent over the system. Application for repair permit included with NOV. **Alternating valve used to switch drainfields, EH walked property and did not observe any discharge of effluent.**	the malfunction asap. 7/28/2021.
	7710 Massey Chapel Rd		10/25/2020	N	Y	8/6/2021	Existing system is discharging effluent to the ground surface. Site has been classified unsuitable for repair. Public sewer is available. **Flow to drainfield restored **	Sewer extension agreement review is pending by City of Durham Public Works Engineering 10/30/2020. Sewer extension agreement approved by City of Durham 11/16/2020. EHS contacted owner for an update. Owner responded they are waiting on a quote and scheduling from a plumbing contractor. 2/26/2021 Sewer connection is cost prohibitive for the property owner. Owner has selected to attempt repair of existing system. Effluent pump was replaced but is discharging near the septic tank when engaged. Contractor is scheduled to evaluate for blockage or damaged pipe. 7/30/2021

7/1/2021	3512 Old Chapel Hill Rd	Surfacing Effluent	8/1/2021	N	Ν	Existing system is failing and non-repairable. Public sewer is available. **NOV Void. Existing discharging sandfilter falls under NC DEQ regulatory authority. DEQ notified via letter.**	
6/29/2021	1203 E OAK DR	Surfacing Effluent	7/29/2021	Ν	Y		Application for sewer connection permit submitted to City/County Inspections 7/5/2021.

		Or	nsite Water Prot	NMENTAL HEALT ection Notices of			LEGEND RED - Indicates updates since last report	
NOV DATE	SUBJECT PROPERTY ADDRESS	TYPE OF VIOLATION	NOV NOV EXPIRATION DATE	mber 2021 FORWARDED TO CO. ATTY?	COMPLIANCE STATUS (YES/NO)	COMPLIANCE DATE	PURPLE - Indicates County Attorney Action Requested/Legal Remedy NOTES	
9/28/2015 8/4/2021 10/11/2021	6101 Cheek Rd	No Subsurface Operator	10/28/2015 9/6/2021 11/11/2021	Y	N		EH has not received system management reports as required by rule. **THIRD NOTICE HAND DELIVERED 10/11/2021**	2/19/2016 - 10-day demand letter issued by County Attorney's Office. 9/30/2016 - EH will follow-up with owner on progress prior to initiation of legal action. NOV to be revisited in 30 days. 3/8/2017 - Requested County Attorney to file lawsuit . 8/31/2018 - System remains non- compliant. No ORC reports have been received as required by rule. 9/30/2018 - System remains non-compliant. Second NOV issued 8/4/2021. EH did not receive USPS return receipt for 2nd notice. 3rd notice hand delivered to site and to home address of property owner 10/11/2021. 10-day demand letter requested 11/30/2021
1/7/2020	8 Steepleton	Surface Discharge	2/7/2020	Y	Ν		Surfacing effluent over pretreatment media and malfunctioning pump controls observed during regular monitoring inspection. System type is pretreated subsurface drip irrigation.	2/27/2020 - EH contacted the system operator for an update. Operator stated owner has signed a work order to repair/replace the malfunctioning control panel and pretreatment media. Scheduling TBD. 5/4/2020 - Per the septic installer, the owner has postponed repair. File forwarded to County Attorney's Office with request for a 10-day demand letter. 12/17/2020 10-day demand letter issued 12/31/2020. Septic contractor notified EHS a price quote for repair will be sent to owner 1/28/2021. Owner is working with installer and has reached out to an engineer to determine potential options for pretreatment alternatives to existing peat modules. 2/23/2021 Contractor states they are still working on quote for pretreatment alternatives. 4/29/2021 EHS contacted septic installer regarding system progress. Contractor has yet to provide a bid. EHS encouraged the contractor to prioritize this project. 8/2/2021 Owner has submitted an application for repair permit. EHS will evaluate parcel to determine if an innovative system type may be utilized to repair/replace the existing failing drip irrigation system 9/29/2021 Owner contacted EHS, states they will be replacing the peat modules with synthetic media. Design proposal from PE forthcoming. 10/11/2021
2/20/2020 9/1/2021		Surfacing Effluent	3/23/2020 10/1/2021	N	N		Existing system is failing. Property owner submitted an application for repair and a construction authorization for installation of a replacement system was issued concurrently with this notice of violation.	2/26/2021 - House is unoccupied, under renovation. Septic repair is pending. Site visit by EHS on 8/10/2021 revealed home has been reoccupied, EHS e-mailed owner for confirmation. Owner states she has not been able to hire a contractor to install system. NOV will be reissued if no progress by 9/1/2021. Second NOV issued 9/1/2021.

							Property owner contacted EH and acknowledged receipt of the NOV. Owner stated she is soliciting bids from plumbers to install the sewer connection. 8/17/2020 EHS directed owner to pump tank as necessary to prevent discharge of effluent until such time owner is able to connect to sewer. 9/17/2020 EHS contacted owner for an update. Owner responded they are managing the malfunction and are working
7/15/2020	802 Hanson Rd	Surfacing Effluent	8/14/2020	N	N	Existing system is failing. Public sewer is available.	on funding for the sewer connection with hopes to complete it within the year. 2/25/2021
9/25/2020	3419 S Alston	Straight Pipe discharge to stream and discharge to ground surface.	10/25/2020	Υ	Ν	Complaint received from City of Durham Stormwater Services of a straight pipe discharging into a stream and surface discharge of effluent above septic tank. EHS visited site and confirmed. City officials have indicated they will also issue a NOV for the straight pipe discharge into the stream.	Property owner contacted EH and stated he will explore the possibility of connecting to public sewer. 9/29/2020 EHS observed and documented unpermitted repair work on system during a site visit. System continues to discharge effluent 12/11/2020. File forwarded to County Attorney's Office with request for a 10-day demand letter. 12/17/2020 10-day demand letter issued 12/31/2020. Site has been classified as unsuitable for repair. Owner is in contact with City Public Works to determine engineering requirements for sewer extension. EHS has directed owner to temporarily pump and haul to abate discharge of effluent while sewer extension is explored. 1/21/2021. Application for sewer extension agreement has been submitted to City Public Works and is pending review as of 3/31/2021. Owner has retained services of an engineer and is meeting with utility contractors to bid the project. Septic tank is being pumped as necessary to prevent discharge. 4/27/2021 Sewer connection extension agreement has been approved by City of Durham. Application for plumbing permit has not yet been submitted 10/29/2021.
7/13/2021	5223 Ephesus Church Rd	Surfacing Effluent	8/13/2021	N	N	Existing system was flooded by City water system maintenance. Prolonged discharge of water main flush onto the property destroyed the drainfield. Connection to public sewer will be facilitated by City of Durham.	EHS contacted owner for an update, left voicemail. 9/30/2021 Letter received from an engineering firm stating they are actively working on the sewer extension design and will be submitting plans to the City of Durham soon 10/1/2021
7/22/2021	213 Snow Hill Rd	Surfacing Effluent	8/23/2021	Y	Ν	Complaint investigation confirmed discharge of effluent over nitrification trenches. Application for repair permit enclosed with NOV.	EHS discussed situation with property manager. Succession growth must be cleared prior to repair evaluation. Property manager instructed to provide receipts for temporary pump and haul until such time the system is repaired. Septic tank was pumped 7/26/2021. Property manager contacted EHS and stated owner is refusing to submit an application for repair. 8/19/2021. File will be forwarded to County Attorney for legal remedy. 9/2/2021 - File forwarded to County Attorney's Office. Complaint drafted by County Attorney's Office and verification signed by OSWP Supervisor 11/10/2021.

7/22/2021	6032 Burgundy Rd	Pump malfunction	8/23/2021	Ν	Y	Pump malfunction discovered during routing monitoring visit. Effluent is backing up into the pump tank freeboard and riser. Owner directed to contact a certified septic installer to repair the pump. for demand letter. 10-day demand letter issued 10/22/2021.
11/29/2021	3616 Alman Dr	Surfacing Effluent	1/3/2022	N	N	Discharge pipe discovered by EHS during complaint investigation. NOV directs owner to connect to public sewer.

ENVIRONMENTAL HEALTH

Onsite Water Protection - Compliant NOVs

July 2021 - June 2022

				II JUNE LOLL				
	SUBJECT PROPERTY		NOV EXPIRATION	FORWARDED	COMPLIANCE STATUS	COMPLIANCE		
NOV DATE	ADDRESS	TYPE OF VIOLATION	DATE	TO CO. ATTY?	(YES/NO)	DATE	NOTES	
6/25/2015		Surfacing effluent, straight pipe from basement plumbing, and property line	7/25/2015					EHS and expressed dismay that system was not in compliance despite
8/3/2021	5114 Leesville Rd	setback violation	9/3/2021	Y	Y	10/14/2021	dye test by EHS confirmed discharge has been abated.**	visit with owner and contractor in attempt to gain compliance.

2/26/2021	143 Twin Oaks Dr	Surfacing Effluent	3/26/2021	Ν	Y	10/14/2021	Effluent is surfacing above tank and throughout drainfield. Public sewer is available. **Septic tank abandoned and sewer connection completed,**	Owner has contacted City regarding sewer connection process. EH provided owner with an application for septic tank abandonment. 4/10/2021 No sewer permit application in LDO. EHS to make a follow up site visit in October. If malfunction is observed a second NOV will be issued. 9/30/2021
							During a site visit for a well permit evaluation, EHS discovered the septic tank has been fitted with a sump pump that is discharging effluent directly to the ground surface. Owner directed to remove pump, temporarily pump and haul, and hire a certified septic contractor to determine existing septic system type prior to any permitting activity. **House has been vacated and the	
9/22/2021	1014 Stallings Rd	Straight Pipe	10/22/2021	N	Y	10/11/2021	pump with straight pipe has been removed.**	
4/28/2021	7011 Russell Rd	Surfacing Effluent	5/30/2021	Ν	Y	10/6/2021	Complaint investigation confirmed discharge of effluent from vicinity of septic tank. Effluent is flowing onto neighboring property. Owner has submitted an application for repair permit. *Drainfield repaired, discharge of effluent has been abated. **	Repair permit issued for exploratory dig 5/4/2021. Septic contractor on site and repair in progress as of 9/30/2021.
1/26/2021	3136 E Geer St	Surfacing Effluent	2/26/2021	Ν	Y	9/30/2021	Complaint received regarding failing septic system. Complaint investigation by EHS confirmed discharge of effluent. **Supply line/clean out repair by owner. Discharge has been abated. * *	Repair permit application submitted by owner. Permit for exploratory dig has been issued. 2/16/2021. Follow-up e-mail sent to owner with a copy of repair permit. E-mail reiterated that owner must contact a certified contractor to repair the system. 6/9/2021
8/12/2021	1224 Bramble Dr	Unapproved Pump Controls	9/16/2021	Ν	Y	9/13/2021	During a routine monitoring inspection EHS observed that effluent pump has been replaced and is connected to house power by an extension cord. Owner directed to hire a contractor to properly wire pump controls within a watertight, corrosion-resistant outside enclosure. **Permanent power has been restored to the system**	
10/28/2015 8/4/2021	3050 Ruth St	No Subsurface Operator	11/27/2015 9/6/2021	Y	Y	9/7/2021		9/30/2016 - Requested 10-day demand letter from County Attorney's office. 9/30/2016 - EH will follow-up with owner on progress prior to initiation of legal action. NOV to be revisited in 30 days. 3/8/2017 - Requested County Attorney file lawsuit . 8/31/2018 - System remains non-compliant. No ORC reports have been received as required by rule. 9/30/2018 - System remains non-compliant. Second NOV issued 8/4/2021. Homeowner contacted EHS requesting list of certified operators 8/19/2021.
							Sewage is backing up into septic tank. Previous bootleg work on system appears to have resulted in part of the drainfield being disconnected and repurposed to receive water from gutter downspouts. Application for repair permit has been received. Property lines must be marked prior to issuing permit for replacement	
7/1/2021	1919 So Hi Dr	Sewage Back Up	8/2/2021	N	Y	8/31/2021	drainfield. **Repair system installed**	Repair permit issued 7/9/2021.

12/18/2020	2717 Comontor Bd	Surfacing Effluent	1/18/2021	Y	Y	2/12/2021	Complaint received regarding failing septic system. Complaint investigation by EHS confirmed discharge of effluent. **Flow was restored to the drainfield with the installation of a new distribution box and extensive	Owner contacted EHS stating a repair application will be submitted 1/21/2021. Owner contacted EHS stating she has contacted a septic installer and will be submitting an application for repair permit. 2/19/2021 Complaint received 3/31/2021 from neighboring property owner regarding continued discharge of effluent and illegal building activity on lot. EHS will follow-up with owner 4/1/2021 and forward to County Attorney if necessary. File forwarded to County Attorney's office 4/5/2021. Owner submitted repair application to EH 4/26/2021. Permit for exploratory dig issued 4/30/2021. Additional complaint of sewage odor and discharge received from neighbor. EHS visited site and instructed property owner to have the tank pumped to prevent discharge. Owner stated that septic installer is scheduled to work on system during the first week of June 5/25/2021 System continues to fail, no repair scheduling has occurred. Requested County Attorney's Office proceed with 10-day demand letter. 6/2/2021 Follow-up site visit by EH confirmed discharge of effluent is ongoing. Photographs and latest complaint message forwarded to County Attorney's Office. 6/8/2021 Second notice issued that includes directive to temporarily pump & haul and to effect repairs as permitted. Notice also includes additional language regarding administrative penalty of \$50/day for non-compliance 7/15/2021. Property owner to immediately have the septic tank pumped and to arrange for a septic contractor to evaluate the mafunction account 7/28/2021
7/15/2021 8/3/2021	2717 Carpenter Rd 4403 Pope Rd	Surfacing Effluent	8/16/2021 9/3/2021	Y N	Y	8/13/2021	clogged pipe repair within the exiting seepage beds.** Complaint investigation confirmed discharge of effluent over the system. Application for repair permit included with NOV. **Alternating valve used to switch drainfields, EH walked property and did not observe any discharge of effluent.**	the malfunction asap. 7/28/2021.
	7710 Massey Chapel Rd		10/25/2020	N	Y	8/6/2021	Existing system is discharging effluent to the ground surface. Site has been classified unsuitable for repair. Public sewer is available. **Flow to drainfield restored **	Sewer extension agreement review is pending by City of Durham Public Works Engineering 10/30/2020. Sewer extension agreement approved by City of Durham 11/16/2020. EHS contacted owner for an update. Owner responded they are waiting on a quote and scheduling from a plumbing contractor. 2/26/2021 Sewer connection is cost prohibitive for the property owner. Owner has selected to attempt repair of existing system. Effluent pump was replaced but is discharging near the septic tank when engaged. Contractor is scheduled to evaluate for blockage or damaged pipe. 7/30/2021

7/1/2021	3512 Old Chapel Hill Rd	Surfacing Effluent	8/1/2021	Ν	Ν	Existing system is failing and non-repairable. Public sewer is available. **NOV Void. Existing discharging sandfilter falls under NC DEQ regulatory authority. DEQ notified via letter.**	
6/29/2021	1203 E OAK DR	Surfacing Effluent	7/29/2021	N	Y		Application for sewer connection permit submitted to City/County Inspections 7/5/2021.

A brief synopsis is provided below for the NOV Report.

6103 (6101) Cheek – Forwarded to B. Wardell for demand letter 11/30/2021

8 Steepleton – Waiting on update from the engineering firm designing the pretreatment replacement.

1712 Doc Nichols – Will call this week for update on contractor selection/timing or install. If no progress then we'll request a demand letter in December.

802 Hanson – Will follow up with owner in December to determine if repair may be an option for the existing system due to prohibitive cost of sewer connection.

3419 S Alston – Pending sewer installation. Site also has stormwater NOV from City of Durham.

5223 Ephesus Church Rd – Pending sewer installation.

213 Snow Hill – Civil complaint drafted by B. Wardell. I signed the verification page 11/10/2021.

6032 Burgundy – 10 day demand letter issued 10/22/2021. No update since.

One new NOV issued, none marked compliant this month.