	SUBJECT PROPERTY			FORWARDED TO CO.	COMPLIANCE		
NOV DATE	ADDRESS	TYPE OF VIOLATION	NOV EXPIRATION DATE	ATTY?	STATUS (YES/NO)	COMPLIANCE DATE	NOTES
							System is surfacing effluent, drainfield totally saturated.
							Also crosses property lines; repair permit issued and
		Surfacing effluent, system crosses					easement recorded, have had preconstruction. **Repair
12/12/2014	1313 Olive Branch	property lines	1/12/2015	N	Y	3/31/2015	system installed**
3/25/2015	13110 Meadowridge	Pump is not working	4/23/2015	N	Y	3/31/2015	Sewage backup. **Pump repaired**
							Application has been made for permanent pump and
							haul. Permit issued 2/2/15 <b>**PUMP &amp; HAUL Operation</b>
1/22/2015	4201 Redwood Rd	Non-permitted system installed	2/22/2015	N	Y	3/30/2015	Permit Issued 3/30/2015**
							No subsurface wastewater system operator. <b>**Owner</b>
9/24/2014	5000 Glenn	No Subsurface Operator	10/24/2014	N	Y	3/30/2015	has hired a certified operator**
2/10/2015	5517 Inverness	Effluent is surfacing over lpp	3/10/2015	N	Y	3/23/2015	Surfacing effluent, **Repaired 3/23/2015**
		Effluent ponding over line 1 and					
2/10/2015	5438 Reese Rd	clean out	3/10/2015	N	Y	3/10/2015	Surfacing effluent, **Repaired 3/10/2015**
							No Subsurface Operator. NOV forwarded to County
							Attorney's office 8/14/2014. <b>**Owner has hired a</b>
6/9/2014	4324 Trenton Rd	No Subsurface Operator	7/9/2014	Y	Y	3/1/2015	certified operator**
							Failing LPP, Homeowner has contracted with McFarland
							as ORC. Will attempt change flow in order to eliminate
		Effluent discharging to ground					failure. 1/28/2015 <b>**System is under active</b>
12/23/2014	1013 Variform	surface	1/23/2014	N	Y	3/1/2015	management by a certified operator**
2/10/2015	115 Belk	Back up.	3/10/2015	N	Y	3/1/2015	Pump not working <b>**pump repaired**</b>
2/10/2015	2602 Sherbrooke	Back up.	3/10/2015	N	Y	3/1/2015	Pump not working <b>**pump repaired**</b>
		not permitted, excavated original					Application has been made for repair; repair permit
1/27/2015	6206 Russell Rd	permitted system	2/27/2015	N	Y	2/16/2015	issued 1/29/15 ** REPAIR INSTALLED 2/16/2015**
							Pump is not working, effluent is backing up and
							surfacing around the tank. ** MALFUNCTIONING
1/27/2015	6625 Russell Rd	Pump is not working	2/27/2015	N	Y	2/8/2015	CONTROL FLOAT REPLACED**
12/23/2015	18 Thistle Trace	Effluent backing up	1/23/2015	N	Y	1/28/2015	Control panel does not work. <b>**REPAIRED**</b> Failing septic system. Non-repairable: Owner is
							attempting to gain access to municipal sewer line. City
							Council approved sewer connection on October 6 2014.
							Property owners are working with the City to facilitate
		Backing up and ponding over septic					the connection. <b>**Connected to municipal sewer</b>
7/31/2014	3629 Freeman	tank	9/1/2014	N	v	1/2/2015	1/2/15**
//31/2014	3029 Freeman	Latik	9/1/2014	IN	T	1/2/2015	1/2/13